

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,012,350 B2  
APPLICATION NO. : 09/803876  
DATED : March 14, 2006  
INVENTOR(S) : C. Theodore Peachee et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1,

Line 3, insert: --RELATED APPLICATIONS This application relates to U.S. Patent Application Serial Nos. 09/817,559, filed March 26, 2001; 09/754,537, filed January 1, 2001; 09/761,125, filed January 16, 2001; 09/824,980, filed April 3, 2001; 09/817,560 filed March 26, 2001; 09/817,687, filed March 26, 2001; and U.S. Patent No. 6,487,769, issued December 3, 2002.--.

Column 6,

Line 60, "648" should be --64B--.

Line 62, "646" should be --64B--.

Line 68, insert: --Terminals 70 and 72 are shown in FIGS. 3 and 5A to be mounted in slots 74 and 76 (FIG. 5C) formed in an end surface 78A of the first end cap 64A. One end of the winding wire 24 is connected to the first terminal 70 while an opposite end of the winding wire 24 is connected to the second terminal 72. Insulating material 77 covers winding wire 24 on both lateral sides of stator core 20. The insulating material 77 is also positioned between the stator segment core 20 and the winding wire 24 as can be seen in Fig. 2A.--.


Column 9,

Line 31, claim 5, after "second", insert --axial--.

Column 10,

Line 27, claim 10, after "second", delete "axial".

Signed and Sealed this  
Eighth Day of November, 2011



David J. Kappos  
*Director of the United States Patent and Trademark Office*